

CO₂ sensor

Snelstart instructie

Quick Guide instruction

Kurzanleitung

Guide d'rapide

zehnder

always the
best climate

Heating

Cooling

Fresh Air

Clean Air



www.zehnder.nl

www.zehnder.be

www.zehnder.co.uk

www.zehnder-systems.de

www.zehnder.fr






30 sec.




HELLERHEID / BRIGHTNESS / HELIGKEIT / NETTÉTÉ



1





2



3



4



1x
 2x
 3x
 4x
 5x
 6x

Fel
 Hoog
 Medium
 Laag
 Waarschuwing
 Uit

Bright
 High
 Medium
 Low
 Warning
 Off

1x
 2x
 3x
 4x
 5x
 6x



Maximal
 Hoch
 Mittel
 Niedrig
 Warnung
 Aus

1x
 2x
 3x
 4x
 5x
 6x






Intense
 Haut
 Moyen
 Bas
 Avertissement
 Éteint

1x
 2x
 3x
 4x
 5x
 6x



5



CO₂ level indicator: 1 green dot (low), 3 green dots (medium), 5 green dots (high)

STAND / POSITION / STUFE / POSITION (PRESET)

NL: Niet mogelijk op alle sensoren.
DE: Nicht bei allen Sensoren möglich.

EN: Not possible on all sensors.
FR: Pas possible sur tous les capteurs.

